


## LAND ROVER ALTERNATORS

**LEA0056**  
**14V / 65A**



Defender 90, 110 2.5D, Discovery TDi,  
Range Rover 2.4 TD, 2.5 TD

1676689M92 / 24199 / 24318 / 2871A165 / 3538541M1 /  
3698016M91 / 3698017M91 / 436145 / 436167 / 714/11400R /  
836640127 / 9124476321 / 92293C1 / ADU9052 / ADU9670 /  
GEU2276 / K311696 / LRA602 / MAR107 / MAR161 / NAB101 /  
PRC6366

**LEA0275**  
**14V / 70A**



Various Applications

110968 / 8EL737664-001 / CA1459IR / NAB300

**LEA0276**  
**14V / 70A**



Various Applications

110969 / 8EL737664-001 / CA1460IR / NAB301

**LEA0453**  
**14V / 120A**



Discovery II 3.9 V8

2542591 / 2542838 / 437425 / SG12B063 / SG12B082 /  
YLE000090 / YLE500090

**LEA0454**  
**14V / 150A**



Discovery II 4.0 V8,  
Range Rover 3.0 TD

2542686 / 2542826 / 437421 / 439463 / A14VI53 / SG15S030 /  
YLE000051 / YLE500180

**LEA0455**  
**14V / 150A**



Freelander 2.0 Td4

0986045251 / 2542343 / 2542602 / 2542605 / 2542852 / 437309 /  
437417 / 439305 / 8EL738130-001 / A14VI34 / A14VI47 / CA1756IR  
DRA3808 / LRA01970 / TG15C038 / YLE000070 / YLE500170

All non - Lucas Elektrik A.Ş. numbers and names are for reference only.

For further inquiries; e-mail:n.guc@lucaselektrik.com Fax:+90 264 276 8771