

LAND ROVER STARTER MOTORS



LES0005
12V / 2.1kW
10 Teeth



(109-110) 2.25 Diesel

26259 / 26321 / 27446 / 27468 / 432574 / 8EA737246-001 / 9000331412 / 9004475056 / CS997 / GEU420 / GEU430 / GEU4430 / GEU4435 / GXE4435 / LRS139 / NSB511



LES0033
12V / 2.1kW
9 Teeth



(109-110) Defender 2.5 Diesel

0986016910 / 26256 / 27425 / 27460 / 432574 / 436052 / 8EA726214-001 / 9004475107 / CS590 / DRS3593 / LRS00574 / LRS574 / NSB512 / PRC3032 / RTC5249



LES0068
12V / 1.7kW
9 Teeth



Defender 3.9 V8, Discovery I & II 3.9 V8, Range Rover 3.9 & 4.3 Vogue SEI & LSE

0001108137 / 0001109040 / 0001110090 / 0001110120 / 0986017440 / 458253 / 458566 / 63226801 / 8EA726213-001 / 8EA737314-001 / CS1049 / CS589 / DRS3198 / DRS3719 / ERR6087 / ESR2191 / LRT00169 / LRT169 / MSN139 / NAD10038 / NAD100380 / NAD101190 / NAD101490



LES0078
12V / 2.0kW
11 Teeth



Freelander 2.0 DI

0986020031 / 128000-1180 / 128000-1181 / 228000-3980 / 228000-3981 / 458288 / 458607 / 8EA730252-001 / 8EA738171-001 / 9004475083 / ADU7457 / DRS3367 / DRS3798 / GNU4558 / JS1314 / JS664 / LRS00677 / LRS677 / LRT00105 / LRT105 / NAD100580



LES0153
24V / 3.5kW
10 Teeth



110 Military & 2.5 Diesel 24V

26387 / 27429 / 27461 / NSB516

All non - Lucas Elektrik A.Ş. numbers and names are for reference only.

For further inquiries;

e-mail:n.guc@lucaselektrik.com

Fax:+90 264 276 8771

www.lucaselektrik.com

